



GV2ME●●

GV2AF01 / GV2AF3 LC1K●● / LC1D●●

1.7 N.m 15 lb.in

1 N.m 7 lb.in
1.7 N.m 15 lb.in
2.5 N.m 20 lb.in

LC1K
LC1D9/12/18
LC125/32

Ø 6 mm

www.schneider-electric.com/site/home

1672546

GV1G09 GV2G4●●

GVAM11

Click! >>

Schneider Electric Industries SAS
35, rue Joseph Monier
92506 Rueil Malmaison
France

www.schneider-electric.com
W9 1645571 0211-08

GV2ME●●
04 - 2016

	mm AWG	mm in	N.m lb-in
x1 x2	1...6 18...10		1.7
x1 x2	6...10 18...10	3/8	15
x1 x2	1...4 18...10		

Click!
TEST

Ø 3 mm
1/8 inch

≤ Ø 3 mm
1/16 inch

⚠ ⚠ DANGER / 危险

HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH

Disconnect all power before servicing equipment.
Failure to follow these instructions will result in death or serious injury.

电击、爆炸或电弧闪光危险
在此电力设备上进行操作时，请先断开所有电源
不遵循上述规定将可能导致人员伤亡。

